## ABSTRACT

A method for winding a stator of a multi-phase motor includes
successively winding each of a plurality of teeth on the stator with a continuous
winding wire to connect each of the phases in the motor together. The wound wire is
disconnected between any two phases where respective ends of the two phases
connected by the winding wire are not neutral ends. A jumper wire is connected
between a neutral end of any one of the phases to a neutral end of at least one other
phase if the neutral end of any one of the phases is not connected to the neutral end
of at least one other phase by the winding wire.